7.5.16 Single storey freestanding building with centrally located front stoep_Stand 975

Address	53 Ninth Street
Stand No.	975
Current Zoning	Residential 1
Year of erection	1933
Architect	Unknown
Heritage Significance	Architectural
Statement of Significance (Heritage importance grading system due to the National Heritage Resources Act 25, 1999)	(a) its importance in the community, or pattern of South Africa's history;
Proposed SAHRA Grading	3A

Site Description

Single storey freestanding residence with centrally located front stoep and two sets of double columns supporting the stoep roof. The three bedroomed house was designed in 1933 and is still in a very good original condition. It is a good example of the freestanding houses in close proximity to Louis Botha Avenue.

Locality Map



Fig. 171 Stand 975 is located along the northern side of Ninth Street in close proximity to Louis Botha Avenue, the Radium Beer Hall and Vangelina Court (Source: City Council of Johannesburg, GIS map)

Original plan for Stand 975




Fig. 172 Plan for proposed new house on Stand 975, Orange Grove One Stand away from Louis Botha Avenue (Source: City Council of Johannesburg, Plans Archive)

Identifying Images



Fig. 173 Good example of single storey corrugated iron roof freestanding residence from 1933 with centrally located stoep and two sets of double columns to support the front stoep (Source: tsica heritage consultants, 2015)



Fig. 174 Good example of a well-designed main entrance stoep with original tiling still in place (Source: tsica heritage consultants, 2015)

Impact of Proposed Development Plan on Heritage

Densities	Recommendations
Medium to Low densities (100-160dph) new buildings suggested maximum scale is 4-6 and a minimum of 2 storeys	Well preserved freestanding single storey residence from around 1930s falls within historical cluster and forms part of a unique streetscape within Orange Grove and it is therefore recommended that the building needs to be preserved.
Transport	Recommendations
Sites fall out of main BRT route transit spine	Not applicable.
Social Cluster	Recommendations
Development	Not applicable.
No social cluster development is ear marked for this area	
Mixed-use Development	Recommendations
Site falls out of mixed-use development	Site is surrounded by single storey residences and it is recommended to maintain building heights to maximum two storeys in close proximity to the residence.

Conservation Management Policies_ Grade 3A_Residential sites

Conservation management plans (CMPs) help to guide the management and running of heritage sites, scenarios, particularly if the heritage buildings or site are earmarked for development. The CMP particularly the policies and guidelines, should be used in the preparation of future expressions of interest, development and feasibility studies, as well as by consultants planning or documenting future work. In conjunction with the SWOT analysis it becomes a useful tool in assessing the opportunities that can arise from the development as well as identify potential risk or threat of the site. In case were development is earmarked for an area certain type of buildings can begin to diminish from a suburb, the purpose of the residential CMP is to make sure that certain type of residential buildings that exhibit, uniqueness, are aesthetically pleasing, or retain a high association with the social or cultural history are conserved and guidelines to their conservation and management are made known

Swot Analysis

Analysis	Result
Strength	Typical freestanding residence with centrally located stoep and half rounded bay windows forms part of a unique streetscape and is in a very good condition and most of the original features are still in place
Weakness	Not applicable
Risk/ Threat	The site is located in an area of medium density development and it may change the character of the site if new buildings are erected near it
Strength/Opportunity	Well preserved 1930s freestanding residence could form part of architectural historical walking tour within Orange Grove

Conservation Management Policies_Residential sites

Views/Vistas

- Retain views of the aesthetically and architecturally significant building
- Ensure that all new buildings erected do not conflict or overpower the heritage buildings

Fabric and Setting

- Retain and restore all the original materials, doors, window panels and other original features of the buildings if alterations are intended for the building
- If additions are to be made, then a contrasting modern materials to be used according to conservation principles

Management

• Establish a team of heritage/conservation professionals which oversee the restoration of historical structures and the introduction of new buildings on site or near the site

Future Development

- Adaptively re-use the buildings in a manner that will not diminish and will ideally enhance their historical or cultural integrity
- Integrate site into tourism route
- Ensure that alterations and additions are made only after consultation with the Provincial Heritage Resources Authority (Gauteng) and in accordance with the National Heritage Resources Act of 1999 section 34 or section 36
- Public facilitation takes place prior to any development

Monika Läuferts le Roux & Judith Muindisi, tsica heritage consultants Office: 5th Avenue, 41 – Westdene – 2092 – Johannesburg; Tel: 011 477-8821 tsica.culturalheritage@gmail.com